

Cincinnati

3959 Fulton Grove Rd.
Cincinnati, Ohio 45245
(513) 752-9111
(513) 752-7973 (Fax)

Cleveland

3100 East 45th Street
Suite 446
Cleveland, Ohio 44127
(216) 916-7378
(513) 752-7973 (Fax)

Services

Phase I ESA's
Phase II Investigations
Asbestos
Energy Efficiency
Lead-Based Paint
Industrial Hygiene
Indoor Air Quality/Mold
Radon
Safety
Training

Asbestos-Containing Materials Inspection

Oakwood Sr/Jr High School
1200 Far Hills Avenue
Oakwood, Ohio 45419

Prepared for:

**Ms. Julie Belden, CPA, MBA
CFO and Treasurer
Oakwood City Schools
20 Rubicon Road
Oakwood, Ohio 45409
(937) 297-5332**

Prepared by:



m.a.c. Paran Consulting Services, Inc.

**George S. Beaudion
Asbestos Hazard Evaluation Specialist #ES31662**

Michelle Paraniuk, M.S., President

Date of Inspection: March 2019

Table of Contents

1.0 Executive Summary

- 1.1 Background
- 1.2 Inspection Results

2.0 Inspection Procedures

- 2.1 General Asbestos Inspection and Sampling Procedures
- 2.2 Method of Sampling and Analysis
 - 2.2.1 Bulk Sample Collection Methods
 - 2.2.2 Analysis of Bulk Samples
 - 2.2.3 Reporting of Analysis Results
 - 2.2.4 Laboratory
- 2.3 Physical and Hazard Assessment
 - 2.3.1 Physical Assessment Factors
 - 2.3.2 Hazard Assessment Factors
 - 2.3.3 Physical & Hazard Assessments of Materials Encountered

3.0 Bulk Sample Data Summary

4.0 Inventory of Asbestos-Containing Materials

Tables	2-1	Factors for Assessing Potential Fiber Release
	2-2	Classifications for Hazard Potential of Friable Asbestos-Containing Materials
	3-1	Bulk Sample Summary
	3-2	Homogeneous Area Descriptions
	4-1	Asbestos-Containing Material Inventory

Appendix A Laboratory Reports

Appendix B Asbestos Hazard Evaluation Specialist License

1.0 Executive Summary

1.1 Background

m.a.c. Paran Consulting Services, Inc. performed an pre-renovation asbestos inspection at the Oakwood Sr/Jr High School, 1200 Far Hills Avenue, Oakwood Ohio. The objectives of the inspection were to (1) identify, by type and location, friable and non-friable asbestos-containing materials [ACM] that were within the structure; (2) assess the current condition of the ACM identified; and, (3) provide estimated quantities of ACM identified. The inspection was conducted by Mr. George S. Beaudion, certified Ohio Asbestos Hazard Evaluation Specialists (License #ES31662) and Mr. W. Scott Carter, certified Ohio Asbestos Hazard Evaluation Specialists (License #ES34717) in March 2019.

1.2 Inspection Results

The following is a summary, based upon findings from both the 1999 and 2019 inspections, of the asbestos-containing (containing >1% asbestos) materials present at the subject property. Please note that the quantities provided in this summary are approximate amounts, and should be verified by an abatement contractor prior to the onset of removal activities.

- **Pipe Insulation** - Approximately 6,511 linear feet of asbestos-containing pipe insulation was identified throughout the building. The material ranges from good to poor condition.
- **Paper Duct Seam Insulation** - Approximately 20 square feet of asbestos-containing paper insulation on HVAC ductwork was identified in the kitchen. The material is in fair condition.
- **Floor Tile and Mastic** - Approximately 23,875 square feet of asbestos-containing floor tile and mastic were identified throughout the building. The materials are in a non-friable condition.
- **Floor Tile** - Approximately 1,244 square feet of asbestos-containing floor tile was identified throughout the building. The material is in a non-friable condition.
- **Black Floor Tile Mastic** - Approximately 8,875 square feet of asbestos-containing floor tile mastic was identified throughout the building. The material is in a non-friable condition.
- **Fitting Insulation** - Approximately 1,026 asbestos-containing cementitious fittings between sections of fiberglass pipe insulation were identified throughout the building. The material ranges from good to fair condition.
- **Tank Insulation** - Approximately 78 square feet of asbestos-containing tank insulation was identified in the building. The material is in fair condition.
- **Canvas with Horse Hair Backing** - Approximately 10,910 square feet of asbestos-containing canvas with horse hair backing was identified in the auditorium of the building. The material is in good condition.
- **Acoustical Plaster** - Approximately 3,052 square feet of asbestos-containing acoustical plaster was identified in the cafeteria of the building. The material is in good condition.
- **Sink Undercoating** - Approximately 12 square feet of asbestos-containing black sink undercoating was identified throughout the building. The material is in a non-friable condition.

- **Vapor Barrier Beneath Gym Floors** - Approximately 9,900 square feet of asbestos-containing vapor barrier material was assumed to be located beneath wood gym floors of the building. The material is in a non-friable condition.
- **Boiler Refractory on Boiler Access Doors** - Approximately 40 square feet of asbestos-containing refractory was assumed to be on boiler access doors. The material is in a non-friable condition.
- **Chalk Board Adhesive** - Approximately 1,520 square feet of asbestos-containing chalk board adhesive was assumed to be located throughout the 1932 building. The material is in a non-friable condition.
- **Dry Erase Board Adhesive** - Approximately 240 square feet of asbestos-containing chalk board adhesive was assumed to be located throughout the 1932 building. The material is in a non-friable condition.
- **Transite Panels** - Approximately 200 square feet of asbestos-containing transite panels was identified in fume hoods in the building. The material is in a non-friable condition.
- **Step Treads** - Approximately 90 square feet of asbestos-containing step treads was identified in stairwell G of the building. The material is in a non-friable condition.
- **Glass Bedding** - Approximately 790 linear feet of asbestos-containing glass bedding material was identified in stairwell G and the 1932 building. The material is in a non-friable condition.
- **Caulking on Exterior Door Frames** - Approximately 560 linear feet of asbestos-containing caulking was identified in the original building and 1932 building. The material is in a non-friable condition.
- **Caulking on Aluminum Window Frames** – Approximately 2,695 linear feet of asbestos-containing caulking on aluminum window frames was identified in the 1932 building. The material is in a non-friable condition.
- **Vapor Barrier Beneath Slate Roofing** - Approximately 20,000 square feet of asbestos-containing black vapor barrier was identified beneath the slate roof of the original building. The material is in a non-friable condition.

Note 1: It should be noted that this inspection report supplements the asbestos inspection reports generated in 2018. Both reports should be referenced to identify laboratory results, approximate material quantity, and locations of asbestos-containing materials.

Note 2: While care was taken during the inspection to identify all asbestos-containing materials, additional materials may be located within non-accessible areas of the structure (e.g., behind walls, above intact ceilings, inside concealed pipe chases, etc.). If, through renovation or demolition these materials are discovered, they should be treated as asbestos-containing until further testing proves otherwise.

2.0 Inspection Procedures

2.1 General Asbestos Inspection and Sampling Procedures

The inspection was performed following a modified protocol of the EPA Asbestos Hazard Emergency Response Act (40 CFR 763.90) commonly known as “AHERA”. Although originally required only for public and private school buildings housing kindergarten through 12th-grade classes, it has become the accepted industry standard for conducting asbestos investigations in all types of buildings. Most recently, the Occupational Safety and Health Administration revised its Asbestos in Construction Industry standard (29 CFR 1926.1101) to reference AHERA as the required method of conducting asbestos inspections in all public and commercial buildings.

The vast majority of physically accessible spaces within the building were accessed and inspected for suspect asbestos-containing materials. The Inspector then grouped suspect materials into homogeneous areas for sampling. A homogeneous area consists of materials with like appearance, color, texture, and application date. A physical assessment (visual observation and touching the material) was also made of the current condition and degree of friability for each identified material (a material is considered friable if it can be crumbled using hand pressure). A list of homogeneous areas identified for this assessment is included on the Bulk Sample Summary Table.

The Inspector assessed all identified asbestos-containing materials. The inspection encompassed both friable and non-friable materials. The Inspector then assumed that the specific material remained homogeneous (based upon the material’s appearance and application) throughout the building. In situations where materials appeared to alternate between asbestos containing and non-asbestos containing, the Inspector looked for visible differences between materials. If differences were not apparent, the Inspector made a professional decision to err on the side of conservatism and assumed that all materials were asbestos-containing.

The Inspector made every effort to locate all asbestos-containing materials identified during the limited inspection; however, should unidentified suspect asbestos-containing materials be discovered, please contact m.a.c. Paran Consulting Services, Inc. for assistance in material identification.

2.2 Method of Sampling and Analysis

2.2.1 Bulk Sample Collection Methods

To avoid disturbing suspected asbestos-containing materials more than necessary and minimize the potential release of asbestos fibers, the Inspector performed bulk sampling in accordance with the industry accepted procedures outlined in the current EPA Guidance Document and the AHERA sampling protocol. Each sample collected was pre-wetted and obtained using a clean coring tool, utility knife, or other appropriate tool. Each sample was then placed in a clean, sealable vial and labeled with a unique sample identification number. Care was taken to obtain a sample that was representative of all layers of a material. To avoid cross-contamination, the tools used for sample collection were thoroughly cleaned before collecting the next sample. If requested, the sample site was labeled with a pre-printed adhesive-backed sample identification tag bearing the corresponding sample identification number. Pertinent sample information was recorded on a standardized bulk sample log sheet including the date of inspection, name of the Inspector, a brief description and the location of the sample, and the type of material sampled (e.g., thermal systems insulation).

2.2.2 Analysis of Bulk Samples

Bulk samples were analyzed for asbestos content by Polarized-Light Microscopy (PLM) and dispersion staining (Method Reference: EPA/600/R-931/116). This analytical method, which EPA currently recommends, for the determination of asbestos in bulk samples, can be used for qualitative identification of six morphologically different types of asbestos fibers: chrysotile, amosite, crocidolite, anthophyllite, tremolite, and actinolite asbestos.

PLM analysis requires the microscopist to take a portion of the sample and treat it with an oil of a specific refractive index. This prepared slide is then subjected to a variety of tests while being viewed under varying polarizations of light. Each asbestos type displays unique characteristic when subjected to these tests. Percentages of the identified types of asbestos are determined by visual estimation.

2.2.3 Reporting of Analysis Results

The method specifies that the asbestos content in a bulk sample shall be estimated and reported as a finite percentage (rounded to the nearest percent) within the range of 0 to 100. Minute quantities of asbestos in bulk samples may be reported as “trace” (tr) or less than 1 percent. The composition of the bulk sample is reported in percentages of asbestos (i.e., chrysotile, amosite, crocidolite, or other) and non-asbestos (i.e., cellulose, fiberglass, mineral wool, synthetic, or other) components. The original laboratory reports are presented in Appendix A.

2.2.4 Laboratory

Analysis of all suspect asbestos-containing materials was performed by Eurofins/CEI Laboratory, 730 SE Maynard Road, Cary NC 27511 using polarized light microscopy. Eurofins/CEI successfully participates in, and is accredited by the National Voluntary Laboratory Accreditation Program (NVLAP), administered by the National Institute of Standards and Technology.

2.3 **Physical and Hazard Assessment**

2.3.1 Physical Assessment Factors

Per AHERA requirements, the Inspector performed a physical assessment of all friable asbestos-containing materials. This involved physically observing and documenting the current condition of each friable material and assessing its potential for future disturbance (or fiber release potential).

The Inspector categorized the materials' current condition as Good, Fair, or Poor. AHERA protocol is not specific as to how these categories are arrived at, but in general the following guideline is used:

- Good – less than 10% area damage
- Fair – more than 10%, but less than 25% area damage
- Poor – more than 25% area damage

The Inspector then made an assessment of the materials' potential for future disturbance (or fiber release potential) using the general factors listed in Table 2-1 on the following page. The first three factors focus on the current condition of the asbestos-containing material. Evidence of deterioration, delamination, physical damage, or water damage indicates that fiber release has occurred, is occurring, or is likely to occur in the future. Such evidence is based on the appearance of the material and/or the presence of dislodged or crumbled material in the surrounding area. The first three factors focus on the potential for fiber release due to disturbance or erosion. Surface erosion is likely to occur when asbestos-containing materials are located in air plenums or near forced-air streams. Exposed and easily accessible materials in areas frequented by building occupants, or subject to mechanical vibrations are more vulnerable to disturbance or damage than materials in other locations.

Table 2-1: Factors for Assessing Potential Fiber Release	
Current Condition of Asbestos-Containing Materials	
<ul style="list-style-type: none"> • Evidence of deterioration or delamination from the underlying surface (substrate) • Evidence of physical damage (e.g., presence of debris) • Evidence of water damage 	
Potential for Future Disturbance, Damage, or Erosion of Asbestos-Containing Material	
<ul style="list-style-type: none"> • Proximity to air plenum or direct airstream • Visibility, accessibility (to building occupants and maintenance personnel), and degree of activity (air movement, vibration, movement of building occupants) • Change in building use 	

2.3.2 Hazard Assessment Factors

Based upon the physical assessment, friable asbestos-containing materials are then given a hazard rank with corresponding response options to aid the building owner in prioritizing response actions. The hazard ranks range from 7 – most hazardous, to 1 – least hazardous as shown in Table 2-2 below. The highest rank is reserved for materials that are “significantly damaged” or material that is so extensively damaged that it requires immediate corrective action. Hazard ranks 4 – 6 reflect materials which are “damaged” with rank 6 indicating a high potential for further damage, and rank 5 indicating a moderate potential for damage. Hazard rank 4 denotes that a material has been damaged; however, the potential for any further damage is low. Hazard ranks 1 – 3 are reserved for materials currently in good condition with future disturbance potentials being high, moderate, or low (3, 2, 1, respectively). Non-friable materials are categorized as non-friable.

Table 2-2: Classifications for Hazard Potential of Friable Asbestos-Containing Materials		
Hazard Rank	Condition	Disturbance Potential
7	Poor	Any
6	Fair	High
5	Fair	Moderate
4	Fair	Low
3	Good	High
2	Good	Moderate
1	Good	Low

2.3.3 Physical and Hazard Assessments of Materials Encountered

The physical and hazard assessments made for all asbestos-containing materials identified during this inspection can be found in Section 4.0 "Inventory of Asbestos-Containing Materials".

3.0 Bulk Sample Data Summary

The following table presents the results of materials sampled.

Table 3-1: Bulk Sample Summary – Oakwood Jr/Sr High School				
Room/Location	Material Description	Homogeneous Area No. (HA)	Sample Number	Laboratory Results
Original Building Room 302	9" Floor Tile (dark brown)	1	1	10% Chrysotile
Original Building Room 302	Yellow Mastic on HA #1	1A	1	2% Chrysotile
Original Building Room 207	9" Floor Tile (dark brown)	1	2	Positive Stop Analysis
Original Building Room 207	Yellow Mastic on HA #1	1A	2	Positive Stop Analysis
Original Building Room 309	Chalk Board Adhesive (white)	2	3	None Detected
Original Building Room 309	Chalk Board Adhesive (white)	2	4	None Detected
Original Building	HVAC Seam Adhesive (grey)	3	5	None Detected
Original Building	HVAC Seam Adhesive (grey)	3	6	None Detected
3 rd Floor Hallway Crawl/Storage Area	Stage Curtain (tan)	4	7	None Detected
3 rd Floor Hallway Crawl/Storage Area	Stage Curtain (tan)	4	8	None Detected
Original Building Room C	Fitting Insulation on Fiberglass Pipe Insulation	5	9	20% Chrysotile 5% Amosite
Original Building Fan Room	Fitting Insulation on Fiberglass Pipe Insulation	5	10	Positive Stop Analysis
Original Building Area off Cafeteria	Fitting Insulation on Fiberglass Pipe Insulation	5	11	Positive Stop Analysis
Original Building Room 105	Preformed Block Pipe Insulation	6	12	30% Chrysotile
Original Building Room 106	Preformed Block Pipe Insulation	6	13	Positive Stop Analysis
Original Building Room 104	Preformed Block Pipe Insulation	6	14	Positive Stop Analysis

Table 3-1: Bulk Sample Summary – Oakwood Jr/Sr High School

Room/Location	Material Description	Homogeneous Area No. (HA)	Sample Number	Laboratory Results
Original Building Room 309	9" Floor Tile (brown, white)	7	15	2% Chrysotile
Original Building Room 309	Black Mastic on HA #7	7A	15	7% Chrysotile
Original Building Room 309	9" Floor Tile (brown, white)	7	16	Positive Stop Analysis
Original Building Room 309	Black Mastic on HA #7	7A	16	Positive Stop Analysis
Original Building Room 309	2' x 2' Ceiling Tile (dimple finish)	8	17	None Detected
Original Building Room 309	2' x 2' Ceiling Tile (dimple finish)	8	18	None Detected
Original Building Room 309	Linoleum Flooring (brown, grey, tan)	9	19	None Detected
Original Building Room 309	Linoleum Flooring (brown, grey, tan)	9	20	None Detected
Original Building Room 300	12" Floor Tile (tan, black, white)	12	21	None Detected
Original Building Room 300	Black Mastic on HA #7	12A	21	3% Chrysotile
Original Building Room 300	12" Floor Tile (tan, black, white)	12	22	None Detected
Original Building Room 300	Black Mastic on HA #7	12A	22	Positive Stop Analysis
Original Building 2 nd Floor Men's R/R	12" Floor Tile (tan, brown, white)	13	23	None Detected
Original Building 2 nd Floor Men's R/R	Yellow Mastic on HA #13	13A	23	None Detected
Original Building 2 nd Floor Men's R/R	12" Floor Tile (tan, brown, white)	13	24	None Detected
Original Building 2 nd Floor Men's R/R	Yellow Mastic on HA #13	13A	24	None Detected

Table 3-1: Bulk Sample Summary – Oakwood Jr/Sr High School

Room/Location	Material Description	Homogeneous Area No. (HA)	Sample Number	Laboratory Results
Original Building Room 210	9" Floor Tile (tan)	14	25	2% Chrysotile
Original Building Room 210	Black Mastic on HA #14	14A	25	2% Chrysotile
Original Building Room 210	9" Floor Tile (tan)	14	26	Positive Stop Analysis
Original Building Room 210	Black Mastic on HA #14	14A	26	Positive Stop Analysis
Original Building Cafeteria Office	Drywall/Compound	15	27	None Detected
Original Building Cafeteria Office	Drywall/Compound	15	28	None Detected
Original Building Room 107A	Drywall/Compound	15	29	None Detected
Original Building Fan Room	Air Cell Pipe Insulation	16	30	65% Chrysotile
Original Building Room C	Air Cell Pipe Insulation	16	31	Positive Stop Analysis
Original Building Room 101A/B	Air Cell Pipe Insulation	16	32	Positive Stop Analysis
Original Building Room 207	9" Floor Tile (white)	17	33	None Detected
Original Building Room 207	Black Mastic on HA #17	17A	33	2% Chrysotile
Original Building Room 207	9" Floor Tile (white)	17	34	None Detected
Original Building Room 207	Yellow Mastic on HA #17	17A	34	None Detected
Original Building Room 207	Carpet Mastic (yellow)	18	35	None Detected
Original Building Room 207	Carpet Mastic (yellow)	18	36	None Detected
Original Building Room 206	12" Floor Tile (beige, blue, white)	20	37	None Detected

Table 3-1: Bulk Sample Summary – Oakwood Jr/Sr High School

Room/Location	Material Description	Homogeneous Area No. (HA)	Sample Number	Laboratory Results
Original Building Room 206	Black Mastic on HA #20	20A	37	None Detected
Original Building Room 206	12" Floor Tile (beige, blue, white)	20	38	None Detected
Original Building Room 206	Black Mastic on HA #20	20A	38	None Detected
Original Building Room 206	12" Floor Tile (deep red)	21	39	None Detected
Original Building Room 206	Black Mastic on HA #21	21A	39	None Detected
Original Building Room 206	12" Floor Tile (deep red)	21	40	None Detected
Original Building Room 206	Black Mastic on HA #21	21A	40	None Detected
Original Building Room 206	Brown Mastic on HA #21	21B	40	3% Chrysotile
Original Building Auditorium	Stage Curtain (blue)	23	41	None Detected
Original Building Auditorium	Stage Curtain (blue)	23	42	None Detected
Original Building Auditorium	Stage Curtain (black)	24	43	None Detected
Original Building Auditorium	Stage Curtain (black)	24	44	None Detected
Original Building Auditorium	Canvas Ceiling Material with Horse Hair	25	45	5% Chrysotile
Original Building Auditorium	Canvas Ceiling Material with Horse Hair	25	46	Positive Stop Analysis
Original Building Auditorium	Canvas Ceiling Material with Horse Hair	25	47	Positive Stop Analysis
Original Building Auditorium	Textured Finish on Walls	26	48	None Detected

Table 3-1: Bulk Sample Summary – Oakwood Jr/Sr High School

Room/Location	Material Description	Homogeneous Area No. (HA)	Sample Number	Laboratory Results
Original Building Auditorium	Textured Finish on Walls	26	49	None Detected
Original Building Auditorium	Textured Finish on Walls	26	50	None Detected
Original Building Auditorium	Textured Finish on Walls	26	51	None Detected
Original Building Auditorium	Textured Finish on Walls	26	52	None Detected
Original Building Auditorium	Step Tread (brown, grey, white)	27	53	None Detected
Original Building Auditorium	Yellow, Brown Mastic on HA #27	27A	53	None Detected
Original Building Auditorium	Step Tread (brown, grey, white)	27	54	None Detected
Original Building Auditorium	Yellow, Brown Mastic on HA #27	27A	54	None Detected
Original Building Auditorium	Glazing on Steel Interior Windows	28	55	None Detected
Original Building Auditorium	Glazing on Steel Interior Windows	28	56	None Detected
Original Building Auditorium Exterior Porch	Acoustical Ceiling Plaster	30	57	None Detected
Original Building Auditorium Exterior Porch	Acoustical Ceiling Plaster	30	58	None Detected
Original Building Auditorium Exterior Porch	Acoustical Ceiling Plaster	30	59	None Detected
Original Building Kitchen	9" Floor Tile (brown, white)	31	60	None Detected
Original Building Kitchen	Black Mastic on HA #31	31A	60	5% Chrysotile
Original Building Kitchen	9" Floor Tile (brown, white)	31	61	None Detected

Table 3-1: Bulk Sample Summary – Oakwood Jr/Sr High School

Room/Location	Material Description	Homogeneous Area No. (HA)	Sample Number	Laboratory Results
Original Building Kitchen	Black Mastic on HA #31	31A	61	Positive Stop Analysis
Original Building Kitchen	Paper Insulation on HVAC Ductwork	32	62	65% Chrysotile
Original Building Kitchen	Paper Insulation on HVAC Ductwork	32	63	Positive Stop Analysis
Original Building Kitchen	Paper Backing on 1' x 2' Ceiling Tiles	33	64	None Detected
Original Building Kitchen	Paper Backing on 1' x 2' Ceiling Tiles	33	65	None Detected
Original Building Cafeteria	12" Floor Tile (tan, black, brown)	35	66	None Detected
Original Building Cafeteria	Black Mastic on HA #35	35A	66	3% Chrysotile
Original Building Cafeteria	12" Floor Tile (tan, black, brown)	35	67	None Detected
Original Building Cafeteria	Black Mastic on HA #35	35A	67	Positive Stop Analysis
Original Building First Floor Hall	12" Ceiling Tile Adhesive (brown)	36	68	None Detected
Original Building Room 106	12" Ceiling Tile Adhesive (brown)	36	69	None Detected
Original Building First Floor Hall	12" Ceiling Tile (medium pin holes)	37	70	None Detected
Original Building Room 106	12" Ceiling Tile (medium pin holes)	37	71	None Detected
Original Building Room 101 A/B	12" Floor Tile (peach, brown, white)	38	72	None Detected
Original Building Room 101 A/B	Black Mastic on HA #38	38A	72	5% Chrysotile
Original Building Room 101 A/B	12" Floor Tile (peach, brown, white)	38	73	None Detected
Original Building Room 101 A/B	Black Mastic on HA #38	38A	73	Positive Stop Analysis

Table 3-1: Bulk Sample Summary – Oakwood Jr/Sr High School

Room/Location	Material Description	Homogeneous Area No. (HA)	Sample Number	Laboratory Results
Original Building	Cove Base Adhesive (tan)	39	74	None Detected
Original Building	Cove Base Adhesive (tan)	39	75	None Detected
Original Building Room 109A	12" Floor Tile (white, green, red, tan)	40	76	None Detected
Original Building Room 109A	Yellow Mastic on HA #40	40A	76	None Detected
Original Building Room 109A	12" Floor Tile (white, green, red, tan)	40	77	None Detected
Original Building Room 109A	Yellow Mastic on HA #40	40A	77	None Detected
Original Building Room 109A	Laboratory Counter Top (black)	41	78	None Detected
Original Building Room 109A	Laboratory Counter Top (black)	41	79	None Detected
Original Building Lower Level Air Handler Area	Tank Insulation	44	80	10% Chrysotile
Original Building Lower Level Air Handler Area	Tank Insulation	44	81	Positive Stop Analysis
Original Building Lower Level Air Handler Area	Tank Insulation	44	82	Positive Stop Analysis
1960 Addition Room 212A	12" Floor Tile (blue, red, white)	45	83	None Detected
1960 Addition Room 212A	Yellow Mastic on HA #45	45A	83	None Detected
1960 Addition Room 212A	12" Floor Tile (blue, red, white)	45	84	None Detected
1960 Addition Room 212A	Yellow Mastic on HA #45	45A	84	None Detected
1960 Addition Room 212A	12" Ceiling Tile Adhesive (brown)	46	85	None Detected
1960 Addition Room 212A	12" Ceiling Tile Adhesive (brown)	46	86	None Detected

Table 3-1: Bulk Sample Summary – Oakwood Jr/Sr High School

Room/Location	Material Description	Homogeneous Area No. (HA)	Sample Number	Laboratory Results
1960 Addition Room 212H	Drywall/Compound	47	87	None Detected
1960 Addition Prep Room D	Drywall/Compound	47	88	None Detected
1960 Addition Room 212H	Drywall/Compound	47	89	None Detected
1960 Addition Room 124	12" Floor Tile (white, green, red)	49	90	None Detected
1960 Addition Room 124	Black Mastic on HA #49	49A	90	None Detected
1960 Addition Room 124	12" Floor Tile (white, green, red)	49	91	None Detected
1960 Addition Room 124	Black Mastic on HA #49	49A	91	None Detected
1960 Addition Room 123	2' x 2' Floor Tile (tan, white, grey)	50	92	None Detected
1960 Addition Room 123	Yellow Mastic on HA #50	50	92	None Detected
1960 Addition Room 123	2' x 2' Floor Tile (tan, white, grey)	50	93	None Detected
1960 Addition Room 123	Yellow Mastic on HA #50	50	93	None Detected
1932 Addition Room S12	12" Floor Tile (beige, brown, white)	53	94	None Detected
1932 Addition Room S12	Black Mastic on HA #53	53A	94	None Detected
1932 Addition Room S12	12" Floor Tile (beige, brown, white)	53	95	None Detected
1932 Addition Room S12	Black Mastic on HA #53	53A	95	None Detected
1932 Addition Room 136	9" Floor Tile (tan)	55	96	5% Chrysotile

Table 3-1: Bulk Sample Summary – Oakwood Jr/Sr High School

Room/Location	Material Description	Homogeneous Area No. (HA)	Sample Number	Laboratory Results
1932 Addition Room 136	Black Mastic on HA #55	55A	96	None Detected
1932 Addition Room 136	9" Floor Tile (tan)	55	97	Positive Stop Analysis
1932 Addition Room 136	Black Mastic on HA #55	55A	97	None Detected
1932 Addition Room 136	9" Floor Tile (brown)	56	98	10% Chrysotile
1932 Addition Room 136	Black Mastic on HA #56	56A	98	None Detected
1932 Addition Room 136	9" Floor Tile (brown)	56	99	None Detected
1932 Addition Room 136	Black Mastic on HA #56	56A	99	None Detected
1932 Addition Room 113	Linoleum Flooring (tan, grey)	57	100	None Detected
1932 Addition Room 113	Green Mastic on HA #57	57A	100	None Detected
1932 Addition Room 113	Linoleum Flooring (tan, grey)	57	101	None Detected
1932 Addition Room 113	Green Mastic on HA #57	57A	101	None Detected
1932 Addition Room 112	Textured Finish on Ceiling	58	102	None Detected
1932 Addition Room 112	Textured Finish on Ceiling	58	103	None Detected
1932 Addition Room 112	Textured Finish on Ceiling	58	104	None Detected
1932 Addition Room 112	12" Floor Tile (tan, brown, white)	59	105	None Detected
1932 Addition Room 112	Yellow Mastic on HA #59	59A	105	None Detected
1932 Addition Room 112	12" Floor Tile (tan, brown, white)	59	106	None Detected

Table 3-1: Bulk Sample Summary – Oakwood Jr/Sr High School

Room/Location	Material Description	Homogeneous Area No. (HA)	Sample Number	Laboratory Results
1932 Addition Room 112	Yellow Mastic on HA #59	59A	106	None Detected
1932 Addition Stairwell G	Step Tread (brown, white)	60	107	3% Chrysotile
1932 Addition Stairwell G	Brown Mastic on HA #60	60A	107	None Detected
1932 Addition Stairwell G	Step Tread (brown, white)	60	108	Positive Stop Analysis
1932 Addition Stairwell G	Brown Mastic on HA #60	60A	108	None Detected
1932 Addition Stairwell G	Caulking on Steel Window Frames	61	109	5% Chrysotile
1932 Addition Stairwell G	Caulking on Steel Window Frames	61	110	Positive Stop Analysis
1932 Addition Stairwell G	Glass Bedding on Steel Windows	62	111	5% Chrysotile
1932 Addition Stairwell G	Glass Bedding on Steel Windows	62	112	Positive Stop Analysis
Original Building	Caulking on Aluminum Window Frames	63	113	None Detected
Original Building	Caulking on Aluminum Window Frames	63	114	None Detected
Original Building	Caulking on Aluminum Window Frames	63	115	None Detected
Original Building	Caulking on Aluminum Window Frames	63	116	None Detected
Original Building	Caulking on Exterior Entrance Door Frames	64	117	2% Chrysotile
Original Building	Caulking on Exterior Entrance Door Frames	64	118	Positive Stop Analysis
1932 Addition	Caulking on Aluminum Window Frames	65	119	None Detected
1932 Addition	Caulking on Aluminum Window Frames	65	120	5% Chrysotile

Table 3-1: Bulk Sample Summary – Oakwood Jr/Sr High School

Room/Location	Material Description	Homogeneous Area No. (HA)	Sample Number	Laboratory Results
1932 Addition	Caulking on Exterior Entrance Door Frames	66	121	5% Chrysotile
1932 Addition	Caulking on Exterior Entrance Door Frames	66	122	Positive Stop Analysis
1932 Addition	Glass Bedding on Leaded Glass Windows	67	123	5% Chrysotile
1932 Addition	Glass Bedding on Leaded Glass Windows	67	124	Positive Stop Analysis
1960 Addition	Caulking on Aluminum Window Frames	68	125	None Detected
1960 Addition	Caulking on Aluminum Window Frames	68	126	None Detected
Original Building	Slate Roofing	69	127	None Detected
Original Building	Slate Roofing	69	128	None Detected
Original Building	Vapor Barrier Beneath Slate Roof	70	129	None Detected
Original Building	Vapor Barrier Beneath Slate Roof	70	130	10% Chrysotile
1932 Addition	Slate Roofing	71	131	None Detected
1932 Addition	Slate Roofing	71	132	None Detected
1932 Addition	Vapor Barrier Beneath Slate Roof	72	133	None Detected
1932 Addition	Vapor Barrier Beneath Slate Roof	72	134	None Detected
Original Building Exterior	Stucco	73	135	None Detected
Original Building Exterior	Stucco	73	136	None Detected
Original Building Exterior	Stucco	73	137	None Detected

Table 3-2 Homogeneous Area Descriptions – Oakwood Jr/Sr High School

HA#	Description of Material – Bold Type Indicates Asbestos-Containing
1	9” Floor Tile – Black/White
1A	Black Mastic on HA #1
2	Chalk Board Adhesive – Original Building
3	HVAC Seam Mastic
4	Stored Stage Curtain – Tan
5	Fitting Insulation on Sections of Fiberglass Pipe Insulation – Original Building
6	Pre-Formed Block Pipe Insulation – Original Building
7	9” Floor Tile – Light Brown with Long White and Brown Streaks
7A	Black Mastic on HA #7
8	2’ x 2’ Ceiling Tile – Dimple Finish
9	Linoleum Flooring – Brown, Grey, Tan
10	Black Vapor Barrier Beneath Slate Roofing – Original Building
11	Slate Roofing – Original Building
12	12” Floor Tile – Tan with Black, White, Tan Streaks
12A	Black Mastic on HA #12
13	12” Floor Tile – Tan with Brown, and White Streaks
13A	Yellow Mastic on HA #13
14	9” Floor Tile – Tan
14A	Black Mastic on HA #14
15	Drywall/Compound – Original Building
16	Air Cell Pipe Insulation
17	9” Floor Tile – White
17A	Black, Brown Mastic on HA #17

Table 3-2 Homogeneous Area Descriptions – Oakwood Jr/Sr High School

HA#	Description of Material – Bold Type Indicates Asbestos-Containing
18	Carpet Mastic – Yellow
19	Dry Erase Board Adhesive – Assumed to be Asbestos-Containing
20	12" Floor Tile – Beige with Blue, White and Brown Streaks
20A	Black Mastic on HA #20
21	12" Floor Tile – Deep Red
21A	Black Mastic on HA #21
22	Sink Undercoating – Black (previously identified as asbestos-containing)
23	Stage Curtain – Blue
24	Stage Curtain – Black
25	Canvas Material with Horse Hair Backing – Original Building Auditorium
26	Textured Finish on Walls – Original Building Auditorium
27	Rubber Step Treads – Brown with Grey and White Flecks
27A	Black, Brown Mastic on HA #27
28	Glazing on Interior Steel Windows – Original Building Auditorium
29	Acoustical Ceiling Plaster – Original Building Auditorium Foyer (previously identified as asbestos-containing)
30	Acoustical Ceiling Plaster – Original Building – Exterior Soffit
31	9" Floor Tile – Light Brown with Long White Streaks
31A	Black Mastic on HA #31
32	Paper Insulation on HVAC Duct Seams – Original Building
33	Paper Backing on 1' x 2' Steel Ceiling Tiles
34	Acoustical Ceiling Plaster – Original Building – Cafeteria (previously identified as asbestos-containing)
35	12" Floor Tile – Tan with Black, Brown and White Streaks
35A	Black Mastic on HA #35

Table 3-2 Homogeneous Area Descriptions – Oakwood Jr/Sr High School

HA#	Description of Material – Bold Type Indicates Asbestos-Containing
36	12" Ceiling Tile Adhesive – Original Building
37	12" Ceiling Tile – Medium Pin Holes – Original Building
38	12" Floor Tile – Peach with Small Brown and White Streaks
38A	Black Mastic on HA #38
39	Cove Base Adhesive – Tan
40	12" Floor Tile – White with Green, Red and Tan Flecks
40A	Yellow Mastic on HA #40
41	Laboratory Counter Tops – Black
42	Vapor Barrier Beneath Original Building Gym Floor (assumed to be asbestos-containing)
43	Refractory Insulation on Inside access doors to Boilers (assumed to be asbestos-containing)
44	Tank Insulation
45	12" Floor Tile – Blue with Red, White and Dark Blue Spots
45A	Yellow Mastic on HA #45
46	12" Ceiling Tile Adhesive – 1932 Addition Building
47	Drywall/Compound – 1932 Addition
48	Dry Erase Board Adhesive – 1932 Addition (assumed to be asbestos-containing)
49	12" Floor Tile – White, Green, Red Mixed
49A	Black Mastic on HA #49
50	2' x 2' Floor Tile – Tan with White and Grey Streaks
50A	Yellow Mastic on HA #50
51	Transite Fume Hood Panels (previously identified as asbestos-containing)
52	Vapor Barrier Beneath 1932 Building Gym Floor (assumed to be asbestos-containing)

Table 3-2 Homogeneous Area Descriptions – Oakwood Jr/Sr High School

HA#	Description of Material – Bold Type Indicates Asbestos-Containing
53	12" Floor Tile – Beige with Brown and White Streaks
53A	Yellow Mastic on HA #53
54	Dry Erase Board Adhesive – 1932 Addition (assumed to be asbestos-containing)
55	9" Floor Tile – Tan
55A	Black Mastic on HA #55
56	9" Floor Tile – Brown
56A	Black Mastic on HA #56
57	Linoleum – Tan with Small Grey Speckles
57A	Green Mastic on HA #57
58	Textured Finish on Ceilings
59	12" Floor Tile – Tan with Dark Brown and White Spots
59A	Yellow Mastic on HA #59
60	Step Treads – Brown with White Streaks – Stairwell G Only
60A	Brown Mastic on HA #60
61	Caulking on Steel Window Frames – Stairwell G
62	Glass Bedding on Steel Window Frames – Stairwell G
63	Caulking on Aluminum Window Frames – Original Building
64	Caulking on Exterior Entrance Door Frames – Original Building
65	Caulking on Aluminum Window Frames – 1932 Building
66	Caulking on Exterior Entrance Door Frames – 1932 Building
67	Glass Bedding on Leaded Glass Windows – 1932 Building
68	Caulking on Aluminum Window Frames – 1960 Building

Table 3-2 Homogeneous Area Descriptions – Oakwood Jr/Sr High School

HA#	Description of Material – Bold Type Indicates Asbestos-Containing
69	Slate Roof – Original Building
70	Vapor Barrier Beneath Slate Roof – Original Building
71	Slate Roof – 1932 Building
72	Vapor Barrier Beneath Slate Roof – 1932 Building
73	Stucco – Original Building

4.0 Inventory of Asbestos-Containing Materials

The following table presents a list of asbestos-containing materials identified during the 2019 asbestos inspection.

Room/Location	Material Type	Condition/ Hazard Rank	Estimated Quantity
Original Building Room 302	9" Floor Tile/Mastic (HA #1/1A)	Non-Friable	600 sf. (beneath carpet)
Original Building Room 301	9" Floor Tile/Mastic (HA #1/1A)	Non-Friable	768 sf. (beneath carpet)
Original Building Room 304	9" Floor Tile/Mastic (HA #1/1A)	Non-Friable	704 sf. (beneath carpet)
Original Building Room 305	9" Floor Tile/Mastic (HA #1/1A)	Non-Friable	880 sf. (beneath carpet)
Original Building Room 306	9" Floor Tile/Mastic (HA #1/1A)	Non-Friable	1,260 sf. (beneath carpet)
Original Building Room 307	9" Floor Tile/Mastic (HA #1/1A)	Non-Friable	704 sf. (beneath carpet)
Original Building Room 307	Fitting Insulation	Good/3	3 fittings (in closet)
Original Building Storage Room by Room 310	Preformed Block Pipe Insulation	Good/2	8 lf.
Original Building Faculty Restroom Near Room 308	Fitting Insulation	Good/3	3 fittings (in wall chase)
Original Building Room 310	9" Floor Tile/Mastic (HA #1/1A)	Non-Friable	840 sf. (beneath carpet)
Original Building Custodial Closet Near Room 309	Fitting Insulation	Good/3	6 fittings (in wall chase)
Original Building Room 309	9" Floor Tile/Mastic (HA #7/7A)	Non-Friable	335 sf. (beneath carpet)
Original Building Room 300	Black Mastic Beneath 12" Floor Tile (HA #12)	Non-Friable	80 sf.
Original Building Third Floor Hallway	Preformed Block Pipe Insulation	Fair/4	30 lf. (above ceiling)
Original Building Room 211	9" Floor Tile/Mastic (HA #1/1A)	Non-Friable	768 sf. (beneath carpet)
Original Building Room 210	9" Floor Tile/Mastic (HA #14/14A)	Non-Friable	768 sf. (beneath carpet)

Room/Location	Material Type	Condition/ Hazard Rank	Estimated Quantity
Original Building Men's Restroom Near Room 211	Fitting Insulation	Good/3	8 fittings (in wall chase)
Original Building Men's Restroom Near Room 211	Preformed Block Pipe Insulation	Fair/4	12 lf. (in chase)
Original Building Room 202	9" Floor Tile/Mastic (HA #1/1A)	Non-Friable	1,056 sf. (beneath carpet)
Original Building Room 209	9" Floor Tile/Mastic (HA #1/1A)	Non-Friable	384 sf. (beneath carpet)
Original Building Room 203	9" Floor Tile/Mastic (HA #1/1A)	Non-Friable	816 sf. (beneath carpet)
Original Building Room 204	9" Floor Tile/Mastic (HA #1/1A)	Non-Friable	768 sf. (beneath carpet)
Original Building Mech/Data Room	Fitting Insulation	Good/3	4 fittings
Original Building Room 208	9" Floor Tile/Mastic (HA #1/1A)	Non-Friable	720 sf. (beneath carpet)
Original Building Room 205	9" Floor Tile/Mastic (HA #1/1A)	Non-Friable	768 sf. (beneath carpet)
Original Building Women's Restroom Near Room 205	Preformed Block Pipe Insulation	Poor/7	30 lf. (in chase)
Original Building Room 207	9" Floor Tile/Mastic (HA #1/1A, #17/17A)	Non-Friable	912 sf. (beneath carpet)
Original Building Room 207	Air Cell Pipe Insulation	Fair/4	5 lf. (above ceiling)
Original Building Room 207	Air Cell Pipe Insulation	Good/3	22 lf. (below ceiling)
Original Building Room 207B	9" Floor Tile/Mastic (HA #1/1A)	Non-Friable	210 sf. (beneath carpet)
Original Building Room 207C	9" Floor Tile/Mastic (HA #1/1A)	Non-Friable	210 sf. (beneath carpet)
Original Building Room 206	Black Mastic Beneath Tile (HA #21A)	Non-Friable	1,368 sf. (beneath carpet)

Room/Location	Material Type	Condition/ Hazard Rank	Estimated Quantity
Original Building Faculty Restroom Near Room 206	Fitting Insulation	Good/3	12 fittings (in wall chase)
Original Building Auditorium Ceiling	Canvas Ceiling Material with Horse Hair	Good/2	9,350 sf.
Original Building Back Entrance to Auditorium	Canvas Ceiling Material with Horse Hair	Good/2	1,560 sf.
Original Building Room S21	Black Mastic Beneath Tile (HA #21A)	Non-Friable	80 sf. (beneath carpet)
Original Building Kitchen	Black Mastic Beneath Tile (HA #31A)	Non-Friable	1,479 sf.
Original Building Kitchen	Air Cell Pipe Insulation	Fair/5	60 lf. (above ceiling)
Original Building Kitchen	Paper Insulation on HVAC Duct	Fair/5	20 sf. (above ceiling)
Original Building Cafeteria	Acoustical Plaster	Good/3	3,052 sf.
Original Building Cafeteria	Black Mastic Beneath Tile (HA #35A)	Non-Friable	2,948 sf.
Original Building Cafeteria	Air Cell Pipe Insulation	Fair/5	70 lf. (above ceiling)
Original Building Back Area off Cafeteria	Black Mastic Beneath Tile (HA #35A)	Non-Friable	728 sf.
Original Building Back Area off Cafeteria	Fitting Insulation	Good/3	25 fittings (above ceiling)
Original Building Fan Room off Cafeteria	Fitting Insulation	Good/3	6 fittings
Original Building Fan Room off Cafeteria	Preformed Block Pipe Insulation	Poor/7	12 lf.
Original Building Rooms 101 A/B off Cafeteria	Black Mastic Beneath Tile (HA #38A)	Non-Friable	588 sf.
Original Building Rooms 101 A/B off Cafeteria	Air Cell Pipe Insulation	Fair/6	6 lf.
Original Building Stairwell Near Cafeteria	Air Cell Pipe Insulation	Fair/6	10 lf. (exposed)

Room/Location	Material Type	Condition/ Hazard Rank	Estimated Quantity
Original Building Custodial Area next to Cafeteria	Air Cell Pipe Insulation	Fair/4	12 lf.
Original Building Custodial Area next to Cafeteria	Air Cell Pipe Insulation	Poor/7	8 lf. (debris on floor)
Original Building Custodial Area next to Cafeteria	Fitting Insulation	Good/3	10 fittings
Original Building Custodial Storage Room	Air Cell Pipe Insulation	Fair/6	30 lf.
Original Building 1 st Floor Hallway	Air Cell Pipe Insulation	Fair/4	272 lf. (above ceiling)
Original Building Women's R/R Near Cafeteria	Air Cell Pipe Insulation	Fair/5	10 lf. (above ceiling)
Original Building Women's R/R Near Cafeteria	Air Cell Pipe Insulation	Fair/4	4 lf. (above ceiling)
Original Building Custodial Area next to Women's R/R	Air Cell Pipe Insulation	Fair/4	12 lf. (in wall chase)
Original Building Mechanical Room	Preformed Block Pipe Insulation	Fair/6	13 lf.
Original Building Air Handler Room off Mechanical Room	Preformed Block Pipe Insulation	Fair/6	48 lf.
Original Building Air Handler Room off Mechanical Room	Preformed Block Pipe Insulation	Fair/5	20 lf.
Original Building Room 109A	Air Cell Pipe Insulation	Good/3	75 lf.
Original Building Connector off Room 109A	Air Cell Pipe Insulation	Good/3	3 lf.
Original Building Kitchen Area off Connector	Air Cell Pipe Insulation	Fair/5	40 lf. (above ceiling)
Original Building Gym (beneath wood floor)	Vapor Barrier	Non-Friable	4,500 sf. (assumed)
Original Building Room 102	Black Mastic Beneath Tile (HA #38A)	Non-Friable	768 sf.
Original Building Room 108	Air Cell Pipe Insulation	Good/2	62 lf. (above ceiling)

Room/Location	Material Type	Condition/ Hazard Rank	Estimated Quantity
Original Building Room 108	Fitting Insulation	Good/2	3 fittings (above ceiling)
Original Building Room 107	Air Cell Pipe Insulation	Good/2	40 lf. (above ceiling)
Original Building Room 107A	Air Cell Pipe Insulation	Good/2	50 lf. (above ceiling)
Original Building Room 103	9" Floor Tile/Mastic (HA #1/1A)	Non-Friable	768 sf. (beneath carpet)
Original Building Men's R/R Near Room 103	Preformed Block Pipe Insulation	Fair/5	4 lf. (above ceiling)
Original Building Custodial Area off Men's R/R	Preformed Block Pipe Insulation	Poor/7	4 lf.
Original Building Room 104	Air Cell Pipe Insulation	Fair/4	35 lf. (above ceiling)
Original Building Room 104	Preformed Block Pipe Insulation	Fair/5	120 lf. (above ceiling)
Original Building Room 104	Fitting Insulation	Good/2	12 fittings (above ceiling)
Original Building Room 105A	Fitting Insulation	Good/3	13 fittings
Original Building Room 105	Preformed Block Pipe Insulation	Fair/5	125 lf. (above ceiling)
Original Building Room 105	Preformed Block Pipe Insulation	Good/3	3 lf.
Original Building Room 106	9" Floor Tile/Mastic (HA #1/1A)	Non-Friable	720 sf. (beneath carpet)
Original Building Room 106	Preformed Block Pipe Insulation	Fair/5	80 lf. (above ceiling)
Original Building Room 110	9" Floor Tile/Mastic (HA #1/1A)	Non-Friable	432 sf. (beneath carpet)
Original Building Room 110 Offices (2)	9" Floor Tile/Mastic (HA #1/1A)	Non-Friable	432 sf. (beneath carpet)
Original Building Pipe Chase Near Room 110	Preformed Block Pipe Insulation	Poor/7	30 lf. (debris on floor)

Room/Location	Material Type	Condition/ Hazard Rank	Estimated Quantity
Original Building Lower Level Custodial Area	Black Mastic Beneath Tile (HA #31A)	Non-Friable	320 sf.
Original Building Lower Level Custodial Area	Preformed Block Pipe Insulation	Good/3	50 lf.
Original Building Lower Level Boiler Room	Preformed Block Pipe Insulation	Good /3	3 lf. (near steps)
Original Building Lower Level Boiler Room	Refractory Insulation on Boiler Access Doors	Non-Friable	40 sf. (assumed)
Original Building Lower Level R/R off Custodial Area	Black Mastic Beneath Tile (HA #31A)	Non-Friable	48 sf.
Original Building Lower Level R/R off Custodial Area	Preformed Block Pipe Insulation	Good/3	6 lf.
Original Building Lower Level Electrical Room (leads to tunnels)	Preformed Block Pipe Insulation	Good/3	50 lf.
Original Building Lower Level Tank/Air Handler Area (leads to tunnels)	Preformed Block Pipe Insulation	Good/3	120 lf.
Original Building Lower Level Tank/Air Handler Area (leads to tunnels)	Preformed Block Pipe Insulation	Fair/5	240 lf.
Original Building Lower Level Tank/Air Handler Area (leads to tunnels)	Tank Insulation	Fair/6	78 sf.
Original Building Lower Level Inside Air Handler Area	Preformed Block Pipe Insulation	Poor/7	12 lf. (debris on floor)
Original Building Lower Level Inside Air Handler Area	Fitting Insulation	Good/3	6 fittings
Original Building Tunnels	Preformed Block Pipe Insulation	Fair/5	1,400 lf.
Original Building Tunnels	Fitting Insulation	Fair/5	68 fittings
Original Building (in hidden wall/pipe chases)	Preformed Block Pipe Insulation	Fair/5	700 lf. (assumed)
Original Building (in hidden wall chases)	Fitting Insulation	Good/3	50 fittings (assumed)

Room/Location	Material Type	Condition/ Hazard Rank	Estimated Quantity
1932 Building Gym (beneath wood floor)	Vapor Barrier	Non-Friable	5,400 sf. (assumed)
1932 Building Gym (corner pipe chases)	Preformed Block Pipe Insulation	Fair/5	30 lf. (2 chases)
1932 Building Room 133D	Preformed Block Pipe Insulation	Fair/4	80 lf. (above ceiling)
1932 Building Locker Room Next to NE Exit Door	Preformed Block Pipe Insulation	Fair/4	80 lf. (above ceiling)
1932 Building Room 132A	Preformed Block Pipe Insulation	Fair/4	40 lf. (above ceiling)
1932 Building Room 131	Chalk Board Adhesive	Non-Friable	192 sf. (assumed)
1932 Building Room 132	Chalk Board Adhesive	Non-Friable	192 sf. (assumed)
1932 Building Room 134	Chalk Board Adhesive	Non-Friable	192 sf. (assumed)
1932 Building Room 135	9" Floor Tile (HA #55)	Non-Friable	572 sf.
1932 Building Room 135	Chalk Board Adhesive	Non-Friable	192 sf. (assumed)
1932 Building Room 136	9" Floor Tile (HA #55, #56)	Non-Friable	672 sf. (2 layers)
1932 Building Room 137	Chalk Board Adhesive	Non-Friable	192 sf. (assumed)
1932 Building Room 138	Chalk Board Adhesive	Non-Friable	192 sf. (assumed)
1932 Building Room 140	Chalk Board Adhesive	Non-Friable	192 sf. (assumed)
1932 Building Room 112	Preformed Block Pipe Insulation	Fair/6	45 lf. (by roll up door)
1932 Building Room 130	Chalk Board Adhesive	Non-Friable	88 sf. (assumed)
1932 Building Room 129	Chalk Board Adhesive	Non-Friable	88 sf. (assumed)

Room/Location	Material Type	Condition/ Hazard Rank	Estimated Quantity
1932 Building Room 128A	Sink Undercoating (HA #22)	Non-Friable	4 sf. (1 sink)
1932 Building Pipe Tunnels	Preformed Block Pipe Insulation	Fair/4	2,200 lf. (estimate)
1932 Building Pipe Tunnels	Fitting Insulation	Good/1	600 fittings (estimate)
1932 Building Stairwell G	Step Treads (HA #60)	Non-Friable	90 sf.
1932 Building Stairwell G	9" Floor Tile/Mastic (HA #7/7A)	Non-Friable	52 sf.
1932 Building Stairwell G	Caulking on Steel Window Frames	Fair/5	40 lf.
1932 Building Stairwell G	Glass Bedding on Steel Windows	Fair/4	160 lf.
1960 Building Room 212D	Black Mastic Beneath Tile (HA #31A)	Non-Friable	260 sf.
1960 Building Room 214	Dry Erase Board Adhesive	Non-Friable	120 sf. (assumed)
1960 Building Room 215	Dry Erase Board Adhesive	Non-Friable	120 sf. (assumed)
1960 Building Room S24	Black Mastic Beneath Tile (HA #31A)	Non-Friable	100 sf.
1960 Building Room 216	Black Mastic Beneath Tile (HA #31A)	Non-Friable	128 sf.
1960 Building Room 217	Sink Undercoating (HA #22)	Non-Friable	8 sf. (1 sink)
1960 Building Room 119	Transite Fume Hood Panels	Non-Friable	80 sf. (2 hoods)
1960 Building Room 117	Transite Fume Hood Panels	Non-Friable	120 sf. (3 hoods)
1960 Building Pipe Tunnels	Fitting Insulation	Good/1	200 fittings (estimate)

Room/Location	Material Type	Condition/ Hazard Rank	Estimated Quantity
Original Building	Caulking on Exterior Entrance Door Frames	Non-Friable	440 lf.
Original Building	Vapor Barrier Beneath Slate Roofing	Non-Friable	20,000 sf. (estimate)
1932 Building	Caulking on Exterior Aluminum Window Frames	Non-Friable	2,655 lf.
1932 Building	Caulking on Exterior Entrance Door Frames	Non-Friable	120 lf.
1932 Building	Glass Bedding on Leaded Glass Windows	Non-Friable	630 lf.

Appendix A
Laboratory Results

Appendix B

Asbestos Hazard Evaluation Specialist License